

Under Review Notification

Raised By: Alex Pharand

Product #: D145-762

Date: 15.03.20

Product Name: SKIDTUBES

Part Number (D-Part and 9-Digit)	Drawing/Document & Current Affected Revision	"Y" or "N" Required for Each Part							Reserved ECN Log Number	Instructions Relevant to Each Part
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review		
D4682-041	D4682 REV C	Y	Y	N	N	Y	Y	N	551	see below
D4682-043	D4682 REV C	Y	Y	N	N	Y	Y	N	551	see below
D4682-7	D4682 REV C	Y	Y	N	N	Y	Y	N	551	see below
D4682-045	D4682 REV C	Y	Y	N	N	Y	Y	N	551	see below
D4682-1/-1F/-5/-5F/-7/-7F	D4682 REV C	Y	Y	N	N	Y	Y	N	551	see below
D4682-9F/-11F/-9/-11	D4682 REV C	Y	Y	N	N	Y	Y	N	551	see below
D4771-041	D4771 REV B	Y	Y	N	N	Y	Y	N	551	see below
D4773-041	D4773 REV B	Y	Y	N	N	Y	Y	N	551	see below
D4770-1/-3F	D4770 REV A	Y	Y	N	N	Y	Y	N	551	see below
D145-762-013/-053/-113	IIN-D117-762 Rev C	Y	Y	N	N	Y	Y	N	551	see below
-153/-015/-055/-115/-155										

Description of Issue:

Due to stainless steel "spring back" after forming, the wearplates do not conform to the drawing and do not allow for a proper fit on the skid tubes.
 Until the drawings are updated and released on ECN15-551, engineering will provide disposition on all non- conforming parts.
 all parts from stock must be pulled and re-worked per engineering instruction.
 production may continue with disposition from engineering to record deviation of wearplates.

D145-762-XXX top level in stock will need to have wearplates reworked

Distribution:

VP Operations

Director of Operations

Director Quality Assurance

Director of Engineering

Chief Engineer

Engineering Project Managers

Engineering Clerk

Customer Support Manager

Production Engineers

Planning Manager

Program Manager

Technical Support